


I<sup>2</sup>C Output to Next Device      Input from I<sup>2</sup>C Master

GND +5V SDA SCL      SCL SDA +5V GND



I<sup>2</sup>C Pull-up Jumper (4.7K)

Barometric Pressure Sensor

Power LED