



***NOTE:**
Revision A & B Boards have a labeling error indicating + and - connections on the power terminal block. The labeling on this page is correct for all revisions. Revision C boards have been corrected for proper PCB labeling. This controller is polarity protected and will not be damaged by incorrect power connections.